


2016L-448.6

625 Ohio Street

OHIO School
1st Floor

471

~~Kitchen~~



Slop sinks in
custodial closets not sampled
only slop sink sampled was
in kitchen